Radial Tear State of Fig. 1A

Suture Repair + Resection






FIG. 1B



Triple Bucket Handle Tear



Suture Repair and Resection


FIG. 1C

FIG. 1D

CMI-II Meniscus

FIG. 2B


FIG. 2A



2

Zone:


Zone 2: Middle, semi- vascularized- "irrepairable" Zone 1: Outer, vascularized zone- "repairable" Zone 3: Inner, avascular zone- "irrepairable"



Collagen Thickness 1-3 mm

FIG. 3B

FIG. 3A



Longitudinal Tear in Avascular Area

FIG. 4A




FIG. 4B




FIG. 5





FIG. 6






FIG. 7

FIG. 8